XTZ750 & TDM850 Oil Pressure Switch

Can be suited also for TDM900


By Gabibbo

As most of us know, the lost oil pressure can generate a several damages on the engine, if it is not stopped in time


This modification, permit to have an alarm, any time the lube oil system doesn't work properly.


So if the oil pressure dropped below the 0,3-0,6 Barg (the set depend by the type of instrument used), an indicator light advice us of the problem.

This can give us enough time to investigate and find out the reason of the miss function, oil level is too low, gear pump don't work, plugs etc.



Instrument Assy





Remove the original Banjo Bolt and replace it with the instrument Assy.

